

Scan Gap Settings

DPI to Scan Gap = 25.4/DPI

| DPI | Scan Gap |
|------|----------|
| 100 | 0.254 |
| 150 | 0.169 |
| 200 | 0.127 |
| 250 | 0.102 |
| 300 | 0.085 |
| 350 | 0.073 |
| 400 | 0.064 |
| 450 | 0.056 |
| 500 | 0.051 |
| 550 | 0.046 |
| 600 | 0.042 |
| 650 | 0.039 |
| 700 | 0.036 |
| 750 | 0.034 |
| 800 | 0.032 |
| 850 | 0.030 |
| 900 | 0.028 |
| 950 | 0.027 |
| 1000 | 0.025 |